

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection: OGM Karl Houskeeper

Inspection Report

Last Inspection:	Tuesday, July 12, 2011			
End Date/Time:	8/18/2011 2:00:00 PM			
Start Date/Time:	8/18/2011 8:00:00 AM			
Inspection Date:	Thursday, August 18, 2011			
Inspection Type:	C0150032 COMPLETE			
Permit Number:				

Inspector: Karl Houskeeper,
Weather: Clear, Temp. 73 Deg. F.
InspectionID Report Number: 2836

Accepted by: jhelfric 9/14/2011

Permitee: GENWAL RESOURCES INC
Operator: GENWAL RESOURCES INC
Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	6,235.80	
Total Disturbed	27.15	
Phase I		
Phase II		
Phase III		

Mineral Ownership

Types of Operations

✓ Federal
✓ Underground

State
Surface

County
Loadout

Fee
Processing

Other
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Checked in at the main office located at the West Ridge Mine. Nobody was available for the inspection. The draftsman provided the required paper work which was reviewed as part of the complete inspection. Proceeded to the Crandall Mine Site unattended for the field portion of the inspection.

Inspector's Signature:

Karla Houskuper

Date

Thursday, Augus 18 2011

OIL, GAS & MINING

Karl Houskeeper,

Permit Number: C0150032 Inspection Type: COMPLETE

Inspection Date: Thursday, August 18, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	~		✓	
2.	Signs and Markers	✓		~	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations	✓		~	
<u></u>	Explosives	~		✓	
6.	Disposal of Excess Spoil, Fills, Benches	✓	V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓	✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	✓			
13.	Revegetation	~			. 🗌
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.8	a Roads: Construction, Maintenance, Surfacing	V			
16.b	o Roads: Drainage Controls	V			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	✓			
20.	Air Quality Permit	V		V	
 21.	Bonding and Insurance	✓		✓	
22.	Other	✓			

Permit Number: C0150032 Inspection Type: COMPLETE

. .

Inspection Date: Thursday, August 18, 2011

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit is effective 05/13/2008 and expires 05/13/2013. Other documents include the following:

- ·Certificate of Insurance issued 06/01/2011 and terminates 06/01/2012.
- Reclamation agreement is dated April 1998 and is signed by both parties.
- ·UPDES permit UT000024368 effective 05/01/2011 and expires midnight 04/30/2016.
- Air Quality permit DAQE-AN0225003-03, issued 03/20/2003.
- ·SPCC Plan dated 11/02/2009.

2. Signs and Markers

The Mine ID sign is posted at the entrance to the permit area from the forest service road. The sign contains the name, permit ID #, address, and phone number of the operator. Sign is leaning a bit, may need to be re secured.

4.a Hydrologic Balance: Diversions

The culvert inlet off from the coal storage pad is half full of sediment and needs to be cleaned.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Second guarter 2011 sediment pond inspection was done on June 2, 2011.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the May 2011 and June 2011discharge monitoring reports. In june 2011 001 (pond discharge exceeded TSS. DEQ was notified.

5. Explosives

The Insurance form does not include coverage for explosive usage. This needs to be added to the form and re-submitted to the Division.

20. Air Quality Permit

Approval Order DAQE-827-01 was modified on March 20, 2003. This modification allowed additional coal handling equipment (conveyors) for the South Crandall Portals. The new approval order, DAQE-AN0225003-03, was effective March 20, 2003.

21. Bonding and Insurance

Insurance is provided through Federal Insurance Co. policy #37104410.